



VISITOR SAFETY ORIENTATION

This form is to be completed by each visitor. This orientation is valid for the calendar year only.

Welcome to Carmeuse Lime & Stone – Dundas Operation. Your safety during your time with us is our primary concern. You will observe during your stay with us that we take safety very seriously. In order for a safe, accident free stay, all visitors must adhere to the following standards, as this is a heavy industrial site designed to manufacture lime that is used in several industries.

With the exception of contractors, truck drivers and delivery personnel, all other personnel are considered visitors, including Carmeuse employees from other locations. Any visitor who intends to travel into a production area is required to complete this orientation.

From Video	Site Specific Info Not Contained in Video
☐ Nothing we do is worth getting injured. ☐ Sign in and out of plant ☐ Wear seat belts, Headlights on, ☐ Be aware of, and stay away from, heavy equipment ☐ Heavy equipment have right of way ☐ Obey speed limit signs ☐ Obey all signage ☐ Smoking allowed only in designated areas ☐ Wear proper PPE ☐ ANSI/CSA approved hard hat, safety glasses and boots (no shoes) ☐ Sleeved shirt (no tank top) ☐ Respirators in dusty environments ☐ Gloves ☐ Beware of surroundings including low hanging beams ☐ Be aware of trip hazards in walkways, such as hose, piping, or stone ☐ Use handrails, and make sure steps are clear. ☐ In dusty areas, ensure your respirator fits properly. ☐ Lime is a corrosive irritant that may irritate wet skin, eyes and lungs – always avoid unnecessary contact. ☐ Wet lime is very slippery ☐ Do not stand under, conveyor systems ☐ Stay clear of counterweights ☐ Stay clear of conveyor systems ☐ Watch for falling material from processes ☐ First aid kits are available throughout the site ☐ Report any injury or incident immediately. ☐ Fire extinguishers are available throughout the site ☐ Stay with your escort at all times. ☐ Carmeuse takes safety very seriously. We expect everyone to leave the way they arrived.	☐ Lime will react vigorously with water. ☐ AED (automated external defibrillator) is available on Firing floor ☐ In case of emergency – ☐ Call 9-911. ☐ There are reference cards throughout the site ☐ Call firing floor: direct line is 905-628-1482 ☐ Site location is 600 Hwy 5, east of Moxley Road, West of Wilkinson Concrete ☐ Do not disturb the scene so that a proper investigation can be conducted ☐ SO₂ and CO may be present in the kiln inlet building. There are detectors and alarms installed – but you must carry an acid gas respirator with you ☐ High visibility clothing is required ☐ You may not be under the influence of illicit drugs or alcohol. Carmeuse reserves the right to require drug and alcohol testing. ☐ There is no smoking in indoors or in company vehicles

1. By signing this document you acknowledge that you have received this brief and understand all items contained therein.
2. All Contractors and Visitors must comply with the *Occupational Health and Safety Act* and its regulations, all instructions in this form, and all other applicable legislative and Company requirements.
3. Failure to comply with any of the aforementioned could result in immediate dismissal from the site and/or termination of your contract.

Hard Hat Sticker #		<i>Sticker must be affixed to hard hat.</i>	
Visitor's Company		Date	
Name of Visitor <i>print</i>		Signature of Visitor	
Carmeuse Contact		Signature	